



Photograph M: Poorly maintained site fencing and weedy growth along San Feliciano Drive.



Photograph N: Dense Project Site oak tree grove along San Feliciano Drive and overhead utility lines.

Source: Christopher A. Joseph & Associates, 2006.



CHRISTOPHER A. JOSEPH & ASSOCIATES
Environmental Planning and Research

Figure V.B-3
Photographs of the Project Site
Photographs M and N